





Egro Preventative Maintenance

Maintenance Cycle 1 (40,000 cycles or 1 year)

iSteam Kit 99PM1-EISTEAM14



	Check and Clean
	Lubricate
	Replace

To Do	Description	PN No.	Qty.	Fig.	Pos.
	Replace: iSteam wand tip	23000098V	1	A	2
	Replace: steam wand O-ring 6.4x1.9	36301050	1	A	2

